







LINCOLN BOULEVARD


COMMUNITY DESIGN OVERLAY DISTRICT

DRAFT (for Area Planning Commission Review on 01/16/08)



Lincoln Boulevard CDO—Potential Historic Resources

POTENTIAL HISTORIC RESOURCES WITHIN THE PROJECT AREA:			
Name	Address	Description	Image
Broadway Elementary School	1015 Lincoln Blvd.	Also called the Spanish Colonial Revival Administration Building, this structure was built in 1936 and is distinguished by the quoined piers, wood framed concrete window grilles, and the centered main entry containing a partially glazed door topped by a segmental arch transom. This structure appears to meet the criteria for listing in the California Register of Historical Resources.	
Department of Water & Power Building	911 Lincoln Blvd.	Built in the 1930s and is distinguished by its wood framed windows, brick facade and the centered main entry which is surrounded by wood crafted trim. This structure appears to meet the criteria for listing in the California Register of Historical Resources.	
Commercial Building	1717 Lincoln Blvd.	Built in the 1920's, the structure is distinguished by its wood framed windows and brick facade. This structure may meet the criteria for listing in the California Register of Historical Resources, pending additional research.	
Commercial Building	1801 Lincoln Blvd.	Built in 1928 and is distinguished by its wood framed windows and uniquely crafted wood cornice. This structure may meet the criteria for listing in the California Register of Historical Resources, pending additional research.	
Commercial Building	1901 Lincoln Blvd.	Built in 1929 and is distinguished by its wood framed windows and uniquely crafted wood cornice. This structure may meet the criteria for listing in the California Register of Historical Resources, pending additional research.	
Commercial Building	2419 Lincoln Blvd.	Built in the late 1920's, the structure is distinguished by its wood framed windows and brick facade. The second floor does appear to be installed at a later time. This structure may meet the criteria for listing in the California Register of Historical Resources, pending additional research.	



SUBJECT

PROPERTY

DRAFT-for discussion purposes only